

## SB - Service Bulletin ASB - Alert Service Bulletin RAS - Repair Approval Sheet

Doc. No.
SHARK\_SB\_003

Sheet/Pages

1/1

Subject:

Announcement of New AFM Revision (German Version).

Date:

Approved by:

Ing. Vladimír Pekár

Head of Design Organisation

Compliance Information:

Mandatory Recommended Optional Informational

Affected Models/ Serial Numbers:

**SHARK 600** 

SH055, SH063, SH135, SH151, SH152

Reason/Purpose:

The purpose of this service bulletin is to announce the release of **Revision B** of the Aircraft Flight Manual (AFM), document number **SHARK600\_MA\_168**, in its German mutation. Operators must ensure that their manuals are up to date to comply with current operational standards.

Description of Issue/Modification:

The German AFM SHARK600\_MA\_168 has been updated to Rev. B, aligning it with the latest English version of SHARK600 MA 075 Rev. E.

Instructions:

A PDF file of SHARK600\_MA\_168 Rev.B accompanies bulletin email, or it can be downloaded from the <u>SHARK.AERO website</u>.

Print the updated AFM pages on A5-sized sheets.

Remove the old pages from your current AFM binder and replace them with the corresponding new pages from Revision B.

Parts Required: NIL

Material Information: NIL

Weight and Balance Information: NIL

Effectivity:

This bulletin applies to SHARK 600 aircraft registered in Germany under DULV or DAeC.